



**NOTICE TO MARINERS**

**NO. 2/ 2018**

**BUOYS' LIGHT**

- General** : **Myanmar-Yangon River Entrance.**
- Amend** : (a) Lower Float Light to *LFl.W.10Sec* 16° 17'.141N 096° 17'.813E  
(b) Upper Float Light to *Fl.R.7Sec* 16° 20'.00N 096° 22'.00 E
- Details** : (I) Mariners are recommended to keep Lower Float (White Light) buoy on the starboard side while entering the channel and on the port side while leaving.  
(II) Upper Float (Red light) buoy on need to kept on the port side while entering and on the starboard side leaving.
- Charts Affected** : Admiralty Charts No. 833,823, NHC Chart No.09 a .
- Source** : Myanmar Port Authority, dated 2<sup>nd</sup> January, 2018.

*Mu Shein Jint.*

Date, 22<sup>nd</sup> January, 2018

Commanding Officer  
Naval Hydrographic Centre  
Myanmar Navy.