


NOTICE TO MARINERS

NO. 5/ 2018

BUOY

- General** : Myanmar-Yangon River Entrance.
- Insert** :  Fl 2.W. 5s Asian Liberty 16° 40'.154 N 096° 14'.42 E
- Details** : A conical shaped wreck buoy has been placed at the above mentioned position .
- Charts Affected** : Admiralty Chart No. 833, NHC Chart No.09^a .
- Source** : Myanmar Port Authority, dated 1st February, 2018.

Mis Hein Jint.

Commanding Officer
Naval Hydrographic Centre
Myanmar Navy.

Date, 13th February, 2018