


NOTICE TO MARINERS

NO. 29/ 2019

BUOY

- General** : Myanmar, Yangon River Approach .
- Delete** :  Asian Liberty 16° 40'.154 N , 096° 14'.42 E
- Detail** : Asian Liberty Buoy had been drifted due to enviromental effect and will not be reinstalled for a period. Mariners are advised to navigate with caution around that area.
- Charts Affected** : Admiralty Chart No. 833, NHC Chart No.09^a .
- Source** : Myanmar Port Authority, dated on 17th June, 2019.

Min Thein Tint.

Commanding Officer

Naval Hydrographic Centre

Myanmar Navy.

Date, 24th June, 2019